

Instructions




UNIT TRANSFERS



Temperature
160 °C*



Time
4 seconds*



Pressure
2 - 6 Bar*



Peel
Hot / Cold
(as for detailed on quality sticker)

*The temperature, time and pressure can vary depending on the type of heat press, garment and logo dimension.

Washing recommendations



Washing
30°C / 40°C



No tumble dryer



Iron
Inside Out
(Máx. 110°C)



Durability
100 washings aprox.



A3 TRANSFER (420 x 297 mm)

Order information



Colours
Pantone Solid Coated
(Black colours, no gradings,
fluor, metallic, reflective)



Files formats
AI / EPS / vector PDF



Files formats
Vectorizing a file
has an extra cost.



Printing garments
Natural and porous synthetics.



Company associated to:



Finishings



Matt
(Default)



Shining



Transparent
poliester paper



Sublimation
blocker



Optional
A3cut
(extracost)



Average elasticity

Unit transfers allow a great versatility of design and application in a wide range of textile products. Designs have to be vectorized and with high definition to get a good quality.

